








1 KF 32-23 NP

73173



● bolt or stud ○ hole ⊗ combination stud ⊗ air inlet

 kg	3,2 kg
	10003022
	K021
	M16x1.5: max. 25 Nm
	M24x1.5: max. 100 Nm

OE Manufacturer/Part No.

Manufacturer	Original Part No.	Model
Mercedes		
Mercedes		Actros MP2 Service Assy.